

THE CORPORATION OF TAY VALLEY TOWNSHIP  
REQUEST FOR PROPOSAL

ENGINEERING SERVICES FOR THE REPLACEMENT OF BOLINGBROKE BRIDGE

CONTRACT #2019-PW-006

ADDENDUM NO. 1

THIS ADDENDUM SHALL BE INCORPORATED INTO THE RFP PACKAGE AND  
SHALL FORM A PART OF THE CONTRACT DOCUMENTS

---

Date Issued: April 9, 2019  
Issued By: Amanda Mabo, Clerk

---

*Please note the following changes, corrections, additions, deletions, information and/or instructions in connection with the RFP Package. Failure to acknowledge receipt of this Addendum as per Part "A" – Information to Bidders may render your submission non-responsive.*

This addendum is to address the following question(s) and clarification(s):

**Clarification 1:**

Please see attached Addendum "D" 2019 OSIM Inspection, by Ainley Graham and Associates Ltd. dated August 29, 2018

End of Addendum 1

Amanda Mabo, Clerk  
[clerk@tayvalleytp.ca](mailto:clerk@tayvalleytp.ca)

**(ID 15-072) - Bolingbroke Bridge**



**Description**

This structure is a Slab on Steel Girder Bridge located on Crow Lake Road, 0.1 km west of Bolingbroke Road. Deck length is 37.0 metres, width of 5.7 metres. The structure accommodates a 5.0 metre wide wearing surface.

**Additional Investigations Required**

- None.

**Maintenance Needs (1-2 years)**

- None.

**Recommended Work**

The structure is generally in fair to poor condition. The deck top, girder ends, pier column connections, structural steel coating, abutment bearings, abutment walls and wingwalls all evidenced severe deterioration. Due to the amount of deterioration throughout the listed elements replacement of structure is recommended in 1 to 5 years. The full extent of the rehabilitation required to address some of the elements, in particular the deck, will likely be more costly than replacing the bridge in it's entirety. An enhanced OSIM should be carried out in 2020 to determine the extent of deterioration of the girders, piers and soffit.

**Summary Action Report**  
**Bolingbroke Bridge**  
**Site No.: 15-072**

Inspection Date 29-Aug-18

Condition Index Value (BCI) 53.0

Next Biennial Inspection 2020

Current Replacement Value \$2,337,693

**Additional Investigations**

Investigation	Priority	Cost	Investigation	Priority	Cost

**Performance Deficiencies**

Element Group	Element	Performance Deficiency

**Maintenance Needs**

Element Group	Element	Maintenance Required	Priority	Comment

**Repair/ Rehabilitation**

Element Group	Element	Repair/Rehabilitation	Priority	Cost
Deck	Deck Top	Replace	1 - 5 years	\$225,000
Barriers	Railing System	Replace	6 - 10 years	\$70,000
Barriers	Parapet Walls	Replace	6 - 10 years	\$10,000
Deck	Soffit (Interior and Exterior)	Repair	6 - 10 years	\$30,000
Beams/MLE's	Girders	Replace	1 - 5 years	\$60,000
Pier	Shafts/Columns/Pile Bents	Repair	1 - 5 years	\$12,000
Coatings	Structural Steel	Repair	1 - 5 years	\$10,000
Abutments	Bearings	Replace	1 - 5 years	\$100,000
Abutments	Abutment Walls	Repair	1 - 5 years	\$19,000
Abutments	Wingwalls	Repair	1 - 5 years	\$12,000

**Total Repair/Rehabilitation Cost** \$548,000

**Total Associated Work Cost** \$327,000

**Total Cost** \$875,000

**Overall Comments**

The structure is generally in fair to poor condition. The deck top, girder ends, pier column connections, structural steel coating, abutment bearings, abutment walls and wingwalls all evidenced severe deterioration. Due to the amount of deterioration throughout the listed elements replacement of structure is recommended in 1 to 5 years. The full extent of the rehabilitation required to address some of the elements, in particular the deck, will likely be more costly than replacing the bridge in it's entirety. An enhanced OSIM should be carrier out in 2020 to determine the extent of deterioration of the girders, piers and soffit.

Inventory Data:			
<b>Structure Name</b>	<input type="text" value="Bolingbroke Bridge"/>	<b>Hwy No.</b>	<input type="text" value="N/A"/>
<b>Cross. Type Over:</b>	<input checked="" type="checkbox"/> Road <input type="checkbox"/> Rail <input type="checkbox"/> Ped. <input type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. <input type="checkbox"/> Other		
<b>Cross.Type Under:</b>	<input type="checkbox"/> Road <input type="checkbox"/> Rail <input type="checkbox"/> Ped. <input checked="" type="checkbox"/> Navig. Water <input type="checkbox"/> Non-Navig. <input type="checkbox"/> Other		
<b>Hwy/Road Name</b>	<input type="text" value="Crow Lake Road"/>		
<b>Structure Location</b>	<input type="text" value="0.1 West of Bolingbroke Road"/>		
<b>Latitude</b>	<input type="text" value="44.759813°"/>	<b>Longitude</b>	<input type="text" value="-76.519657°"/>
		<b>Cur. Rep. Value**</b>	<input type="text" value="\$2,337,693"/>
<b>Owners</b>	<input type="text" value="Tay Valley Township"/>	<b>Heritage Status</b>	<input type="text" value="No Considered"/>
<b>MTO Region</b>	<input type="text" value="Eastern"/>	<b>Road Class</b>	<input type="text" value="Local"/>
<b>MTO District</b>	<input type="text"/>	<b>Lane Type</b>	<input type="text"/>
<b>Old County</b>	<input type="text" value="Lanark"/>	<b>Posted Speed</b>	<input type="text" value="40"/>
<b>Ward</b>	<input type="text" value="Sherbrooke"/>	<b>AADT</b>	<input type="text" value="200"/>
		<b>No. Lanes</b>	<input type="text" value="1"/>
<b>Structure Type</b>	<input type="text" value="Slab on Steel Girders"/>	<b>Inspection Route Sequence</b>	<input type="text"/>
<b>Total Deck Length</b>	<input type="text" value="37.0"/> m	<b>Interchange Number</b>	<input type="text"/>
<b>Overall Str. Width</b>	<input type="text" value="5.7"/> m	<b>Interchange Structure Number</b>	<input type="text"/>
<b>Total Deck Area</b>	<input type="text" value="210.9"/> m <sup>2</sup>	<b>Detour Length Around Bridge</b>	<input type="text" value="28"/> km
<b>Roadway Width</b>	<input type="text" value="5.0"/> m	<b>Fill on Structure</b>	<input type="text" value="0"/> m
<b>Skew Angle</b>	<input type="text" value="0"/> Degrees	<b>Direction of Structure</b>	<input type="text" value="North to South"/>
<b>No. of Spans</b>	<input type="text" value="3"/>	<b>Special Routes:</b>	<b>School Transit</b> <input checked="" type="checkbox"/> <b>Bicycle Truck</b> <input type="checkbox"/>
<b>Span Lengths</b>	<input type="text" value="12.3, 12.3, 12.3"/> m	**Current Replacement Value is based on in kind replacement of the existing structure and calculated using benchmark costs. Capital planning should be consider site specific cost factors and requirements for widening or lengthing of the structure.	
Historical Data:			
<b>Year Built</b>	<input type="text" value="1930"/>	<b>Year of Last Major Rehab.</b>	<input type="text" value="2012"/>
<b>Last OSIM Inspection</b>	<input type="text" value="2016"/>	<b>Last Evaluation</b>	<input type="text" value="2008"/>
<b>Last Enhanced OSIM</b>	<input type="text" value="N/A"/>	<b>Current Load Limit</b>	<input type="text" value="14"/> tonnes
<b>Last Underwater Inspec.</b>	<input type="text" value="N/A"/>	<b>Load Limit By-Law #</b>	<input type="text" value="N/A"/>
<b>Last Condition Survey</b>	<input type="text" value="N/A"/>	<b>By-Law Expiry Date</b>	<input type="text" value="N/A"/>
<b>Rehab History: (Date / Description)</b>			
1974 - Deck Replaced			
2003 - Approaches resurfaced, hot rubberized sealant placed in expansion joints, beams & girders 4 m at E. Abutment and 1m at W. Abutment were hand cleaned & painted.			
2009 - Repairs to girder flanges, reinforcement of webs and hand cleaned and painted 1.5 m of girder ends.			
2010 - Rehabilitation of concrete pier pedestals			
2012 - Full depth deck repairs and stringer replacement at the south end			

<b>Field Inspection Information:</b>				
<b>Date of Inspection:</b>	August 29, 2018	<b>Type of Inspection:</b>	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM
<b>Inspector:</b>	Bill Harvey			
<b>Others in Party:</b>	Steve Oliver			
<b>Equipment Used:</b>	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.			
<b>Weather:</b>	Sunny			
<b>Temperature:</b>	30 C°			
<b>Additional Investigations Required:</b>		Priority		
		None	Normal	Urgent
Material Condition Survey				
	Detailed Deck Condition Survey:	X		
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	X		
	Concrete Substructure Condition Survey:	X		
	Detailed Coating Condition Survey:	X		
	Detailed Timber Investigation:	X		
	Post-Tensioned Strand Investigation:	X		
Underwater Investigation:		X		
Fatigue Investigation:		X		
Seismic Investigation:		X		
Structure Evaluation:		X		
Monitoring				
	Monitoring of Deformations, Settlements and Movements:	X		
	Monitoring Crack Widths:	X		
<b>Investigation Notes:</b>				
<b>Overall Structure Notes:</b>				
<b>Recommended Work on Structure:</b>	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> Replace
<b>Timing of Recommended Work:</b>		<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years	
<b>Overall Comments:</b>	The structure is generally in fair to poor condition. The deck top, girder ends, pier column connections, structural steel coating, abutment bearings, abutment walls and wingwalls all evidenced severe deterioration. Due to the amount of deterioration throughout the listed elements replacement of structure is recommended in 1 to 5 years. The full extent of the rehabilitation required to address some of the elements, in particular the deck, will likely be more costly than replacing the bridge in it's entirety. An enhanced OSIM should be carrier out in 2020 to determine the extent of deterioration of the girders, piers and soffit.			
<b>Date of Next Inspection:</b>	2020			

**Suspected Performance Deficiencies**

- |   |                                |                              |
|---|--------------------------------|------------------------------|
| 01 Load carrying capacity                           | 07 Jammed expansion joint      | 13 Flooding/channel blockage |
| 02 Excessive deformations (deflections & rotations) | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 03 Continuing settlement                            | 09 Rough riding surface        | 15 Unstable embankments      |
| 04 Continuing movements                             | 10 Surface ponding             | 16 Other                     |
| 05 Seized bearings                                  | 11 Deck drainage               |                              |
| 06 Bearing not uniformly loaded/unstable            | 12 Slippery surfaces           |                              |

**Maintenance Needs**

- |  |                                 |  |
|--|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance   | 07 Repair to Structural Steel   | 13 Erosion Control at Bridges            |
| 02 Bridge Cleaning                     | 08 Repair of Bridge Concrete    | 14 Concrete Sealing                      |
| 03 Bridge Handrail Maintenance         | 09 Repair of Bridge Timber      | 15 Rout and Seal                         |
| 04 Painting Steel Bridge Structures    | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage                  |
| 05 Rehab History: (Date / Description) | 11 Animal/Pest Control          | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance          | 12 Bridge Surface Repair        | 18 Other                                 |

Element Data		Bridge Name		Bolingbroke Bridge				
Element Group:	Deck	Length:	37.0					
Element Name:	Deck Top (Exposed Wearing Surface)	Width:	5.7					
Location:	North to South	Height:	N/A					
Material:	Cast-in-Place Concrete	Count (items):	1					
Element Type:	Thin-Slab	Total Quantity:	210.9		m <sup>2</sup>			
Environment:	Severe	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m <sup>2</sup>		64.7	110.0	36.2			
Comments:	The deck was difficult to inspect due to the amount of debris. Severe delaminations (30.0 m <sup>2</sup> ) and wide transverse cracking (5.7 m <sup>2</sup> ), light spalling (0.3 m <sup>2</sup> ), narrow to medium cracking, light scaling and light abrasions (0.2 m <sup>2</sup> ). A detailed deck condition survey is recommended to determine the full extent of deterioration.							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years	Urgent	X	1 year	2 years
- Replace					02 - Bridge Cleaning - Remove debris from the deck.			

Element Group:	Approaches	Length:	6.0					
Element Name:	Wearing Surface	Width:	5.0					
Location:	North and South	Height:	N/A					
Material:	Asphalt	Count (items):	2					
Element Type:		Total Quantity:	60.0		m <sup>2</sup>			
Environment:	Severe	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m <sup>2</sup>		36.2	20.0	3.8			
Comments:	Medium to severe transverse cracking (3.7 m <sup>2</sup> ), light potholes (0.1 m <sup>2</sup> ), light to medium raveling and asphalt patch localized at the deck joint. The majority of deterioration was observed on the south approach.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent		1 year	2 years

Element Group:	Barriers	Length:	35.2					
Element Name:	Railing System	Width:	N/A					
Location:	East and West	Height:	N/A					
Material:	Aluminum	Count (items):	2					
Element Type:	3-Rail Aluminum Stanchion	Total Quantity:	70.4		m			
Environment:	Severe	Limited Inspection						
Protection System:						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		58.4	8.0	4.0			
Comments:	Several areas of collision damage and light to medium abrasion were noted in both railing systems. Collision damage with a light perforation was observed on the west railing system							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
		1-5 years	X	6-10 years	Urgent		1 year	2 years
- Replace								

Element Group:	Barriers			Length:	0.9		
Element Name:	Parapet Walls			Width:	0.30		
Location:	NE, NW, SE and SW			Height:	1.00		
Material:	Cast-in-Place Concrete			Count (items):	4		
Element Type:	Concrete End-Post (Interior and Exterior)			Total Quantity:	8.3 m <sup>2</sup>		
Environment:	Severe			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m <sup>2</sup>		1.1	3.6	3.6		
Comments:	Medium spalling (0.5 m <sup>2</sup> ), light delamination (0.2 m <sup>2</sup> ), medium to wide cracking (0.2 m <sup>2</sup> ), medium to severe scaling (2.2), light disintegration(0.3 m <sup>2</sup> ), light abrasions (0.2 m <sup>2</sup> ) and hairline to narrow cracking. A benchmark was noted on the southeast end post and a plaque on the northeast						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
		1-5 years	X	6-10 years		Urgent	1 year
- Replace							

Element Group:	Decks			Length:	37.0		
Element Name:	Soffit - Thin Slab			Width:	0.4		
Location:	East and West			Height:	0.2 (Fascia)		
Material:	Cast-in-Place Concrete			Count (items):	2		
Element Type:	Thin Slab - Exterior			Total Quantity:	44.4 m <sup>2</sup>		
Environment:	Moderate			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m <sup>2</sup>		22.6	20.0	1.8		
Comments:	Light to medium delaminations (0.5 m <sup>2</sup> ), light to medium spalling (0.5 m <sup>2</sup> ), medium to wide cracking (0.8 m <sup>2</sup> ), light to medium scaling, light scaling and rust staining. It's recommended that a enhanced OSIM be conducted in 2020 in order to properly examine the interior and exterior soffits.						
Recommended Work:	X	Rehab		Replace	Maintenance Needs:		
		1-5 years	X	6-10 years		Urgent	1 year
- Concrete repair and crack injection							

Element Group:	Decks			Length:	37.0		
Element Name:	Soffit - Thin Slab			Width:	4.9		
Location:	Interior			Height:	N/A		
Material:	Cast-in-Place Concrete			Count (items):	1		
Element Type:	Thin Slab - Interior			Total Quantity:	181.3 m <sup>2</sup>		
Environment:	Benign			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m <sup>2</sup>		140.8	40.0	0.5		
Comments:	Light to medium spalling (0.5 m <sup>2</sup> ), localized medium honeycombing, rust staining and hairline to narrow cracking with moisture staining. It's recommended that a enhanced OSIM be conducted in 2020 in order to properly examine the interior and exterior soffits.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years		Urgent	1 year

Element Group:	Beams/MLÉ's		Length:	37.00		
Element Name:	Girders		Width:	0.24		
Location:	East and West		Height:	0.66		
Material:	Steel		Count (items):	2		
Element Type:	I - Type		Total Quantity:	151.0		m <sup>2</sup>
Environment:	Moderate		Limited Inspection			
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m <sup>2</sup>		76.0	60.0	15.0	
Comments:	The coating on the north end of the girders have failed and medium to severe corrosion is evident. The girder ends on the south exhibited light to medium corrosion. Light to medium corrosion was evident throughout the entire lengths of both the east and west girders. Misalignment was noted between east and west girders over the south pier. It's recommended that a enhanced OSIM be conducted in 2020 in order to properly examine the girders.					
Recommended Work:		Rehab	X	Replace	Maintenance Needs:	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
- Replace						

Element Group:	Beams/MLÉ's		Length:	4.70		
Element Name:	Floor Beams		Width:	0.17		
Location:			Height:	0.38		
Material:	Steel		Count (items):	8		
Element Type:	I - Type		Total Quantity:	47.8		m <sup>2</sup>
Environment:	Benign		Limited Inspection			
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m <sup>2</sup>		47.8	0.0	0.0	
Comments:	Localized light corrosion beginning to form					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Beams/MLÉ's		Length:	4.10		
Element Name:	Stringers		Width:	0.11		
Location:	Underside of Deck		Height:	0.23		
Material:	Steel		Count (items):	36		
Element Type:	I - Type		Total Quantity:	36		each
Environment:	Benign		Limited Inspection			
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	each		36	0	0	
Comments:	The stringers were in generally good condition exhibiting light corrosion and localized medium corrosion along the top flange.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years



Element Group:	Pier		Length:	N/A		
Element Name:	Bearings		Width:	N/A		
Location:	North and South Pier		Height:	N/A		
Material:	Steel		Count (items):	4		
Element Type:	Steel Shoe Plates		Total Quantity:	4 each		
Environment:	Benign		Limited Inspection	X		
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m <sup>2</sup>			4	0	
Comments:	Limited inspection due to access. The area observed evidenced light to medium corrosion. It's recommended that an enhanced OSIM be conducted in 2020.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Piers		Length:	1.0		
Element Name:	Shafts/Columns/Pile Bents		Width:	1.0		
Location:	NE, NW, SE and SW		Height:	1.3		
Material:	Cast-in-Place Concrete		Count (items):	4		
Element Type:	Pier Footing and Pedestal		Total Quantity:	20.8 m <sup>2</sup>		
Environment:	Benign		Limited Inspection			
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m <sup>2</sup>		11.4	6.0	3.4	
Comments:	Light to medium delamination (0.8 m <sup>2</sup> ) localized in the footings, medium to wide cracking (0.5 m <sup>2</sup> ), medium to severe scaling (2.1 m <sup>2</sup> ), light scour and erosion.					
Recommended Work:	X	Rehab		Replace	Maintenance Needs:	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
- Repair						

Element Group:	Piers		Length:	0.2		
Element Name:	Shafts/Columns/Pile Bents		Width:	0.2		
Location:	NE, NW, SE and SW		Height:	6.0		
Material:	Steel		Count (items):	4		
Element Type:	Pier Column		Total Quantity:	28.8 m <sup>2</sup>		
Environment:	Benign		Limited Inspection			
Protection System:	Paint					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m <sup>2</sup>		16.8	10.0	2.0	
Comments:	Medium to severe corrosion (2.0 m <sup>2</sup> ) localized at the connections to the pedestals, light corrosion observed throughout. Section loss and perforations were evident throughout the connections.					
Recommended Work:	X	Rehab		Replace	Maintenance Needs:	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
- Repair						

<b>Element Group:</b>	Piers		<b>Length:</b>	0.18		
<b>Element Name:</b>	Shafts/Columns/Pile Bents		<b>Width:</b>	4.30		
<b>Location:</b>	Underside of Deck		<b>Height:</b>	0.07		
<b>Material:</b>	Steel		<b>Count (items):</b>	4		
<b>Element Type:</b>	Horizontal Bracing		<b>Total Quantity:</b>	4		each
<b>Environment:</b>	Benign		Limited Inspection			
<b>Protection System:</b>	Paint					Perform. Deficiencies
<b>Condition Data:</b>	Units each	Exc.	Good 4	Fair 0	Poor* 0	
<b>Comments:</b>	Evidence of light corrosion forming					
<b>Recommended Work:</b>		Rehab		Replace	<b>Maintenance Needs:</b>	
		1-5 years		6-10 years	Urgent	1 year 2 years

<b>Element Group:</b>	Piers		<b>Length:</b>	N/A		
<b>Element Name:</b>	Shafts/Columns/Pile Bents		<b>Width:</b>	N/A		
<b>Location:</b>	East and West		<b>Height:</b>	N/A		
<b>Material:</b>	Steel		<b>Count (items):</b>	2		
<b>Element Type:</b>	Cross Bracing		<b>Total Quantity:</b>	2		each
<b>Environment:</b>	Moderate		Limited Inspection			
<b>Protection System:</b>	Paint					Perform. Deficiencies
<b>Condition Data:</b>	Units each	Exc.	Good 2	Fair 0	Poor* 0	
<b>Comments:</b>	Evidence of light corrosion forming					
<b>Recommended Work:</b>		Rehab		Replace	<b>Maintenance Needs:</b>	
		1-5 years		6-10 years	Urgent	1 year 2 years

<b>Element Group:</b>	Coatings		<b>Length:</b>	N/A			
<b>Element Name:</b>	Structural Steel		<b>Width:</b>	N/A			
<b>Location:</b>	Structural Steel Members		<b>Height:</b>	N/A			
<b>Material:</b>	Paint		<b>Count (items):</b>	1			
<b>Element Type:</b>			<b>Total Quantity:</b>	329.2		m <sup>2</sup>	
<b>Environment:</b>	Benign		Limited Inspection				
<b>Protection System:</b>	Paint					Perform. Deficiencies	
<b>Condition Data:</b>	Units m <sup>2</sup>	Exc.	Good 50.0	Fair 234.2	Poor* 45.0		
<b>Comments:</b>	Undercutting, blisters and medium to severe corrosion throughout the girder exteriors and ends. Light to medium corrosion throughout remaining steel members.						
<b>Recommended Work:</b>		Rehab	X	Replace	<b>Maintenance Needs:</b>		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	
- Replace							

<b>Element Group:</b>	Abutments		<b>Length:</b>	N/A		
<b>Element Name:</b>	Bearings		<b>Width:</b>	N/A		
<b>Location:</b>	North and South Abutment Walls		<b>Height:</b>	N/A		
<b>Material:</b>	Steel Plate		<b>Count (items):</b>	4		
<b>Element Type:</b>	Abutment Bearings		<b>Total Quantity:</b>	4 each		
<b>Environment:</b>	Benign		Limited Inspection	X		
<b>Protection System:</b>	None					Perform. Deficiencies
<b>Condition Data:</b>	Units m <sup>2</sup>	Exc.	Good	Fair	Poor*	
				4	0	
<b>Comments:</b>	Limited inspection due to line of sight. The areas of the bearings that were observed evidenced medium to severe corrosion and medium deformations. An enhanced OSIM is recommended in 2020 to properly inspect the bearings.					
<b>Recommended Work:</b>		Rehab	X	Replace	<b>Maintenance Needs:</b>	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
- Replace						

<b>Element Group:</b>	Abutments		<b>Length:</b>	N/A		
<b>Element Name:</b>	Abutment Walls		<b>Width:</b>	5.7		
<b>Location:</b>	North		<b>Height:</b>	3.0		
<b>Material:</b>	Cast-in-Place Concrete		<b>Count (items):</b>	1		
<b>Element Type:</b>			<b>Total Quantity:</b>	17.1 m <sup>2</sup>		
<b>Environment:</b>	Benign		Limited Inspection			
<b>Protection System:</b>	None					Perform. Deficiencies
<b>Condition Data:</b>	Units m <sup>2</sup>	Exc.	Good	Fair	Poor*	
				5.8	11.3	
<b>Comments:</b>	The previous patchwork has debonded from the wall. Severe delaminations (4.9 m <sup>2</sup> ), medium to severe spalling (3.5 m <sup>2</sup> ) and light to medium cracking throughout. The northeast corner exhibited severe scaling (2.0 m <sup>2</sup> ), severe disintegration (0.9 m <sup>2</sup> ) and erosion.					
<b>Recommended Work:</b>	X	Rehab		Replace	<b>Maintenance Needs:</b>	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
- Concrete repair and crack injection						

<b>Element Group:</b>	Abutments		<b>Length:</b>	N/A		
<b>Element Name:</b>	Ballast Walls		<b>Width:</b>	N/A		
<b>Location:</b>	North and South		<b>Height:</b>	N/A		
<b>Material:</b>	Cast-In-Place Concrete		<b>Count (items):</b>	2		
<b>Element Type:</b>			<b>Total Quantity:</b>	m <sup>2</sup>		
<b>Environment:</b>	Benign		Limited Inspection	X		
<b>Protection System:</b>	None					Perform. Deficiencies
<b>Condition Data:</b>	Units m <sup>2</sup>	Exc.	Good	Fair	Poor*	
<b>Comments:</b>	Limited access due to access.					
<b>Recommended Work:</b>		Rehab		Replace	<b>Maintenance Needs:</b>	
		1-5 years		6-10 years	Urgent	1 year 2 years

<b>Element Group:</b>	Abutments		<b>Length:</b>	2.3		
<b>Element Name:</b>	Wingwalls		<b>Width:</b>	N/A		
<b>Location:</b>	NE, NW, SE and SW Quadrants		<b>Height:</b>	1.6		
<b>Material:</b>	Cast-In-Place Concrete		<b>Count (items):</b>	4		
<b>Element Type:</b>			<b>Total Quantity:</b>	14.7		m <sup>2</sup>
<b>Environment:</b>	Moderate	Limited Inspection				
<b>Protection System:</b>	None					Perform. Deficiencies
<b>Condition Data:</b>	Units m <sup>2</sup>	Exc.	Good 2.5	Fair 7.5	Poor*	
<b>Comments:</b>	The length and height were taken as an average to determine the total quantity. Light to medium spalling (0.4 m <sup>2</sup> ), localized severe scaling (3.8 m <sup>2</sup> ), localized severe disintegration (0.5 m <sup>2</sup> ), hairline to narrow cracking, light honey combing and light to medium scaling evidenced throughout all walls.					
<b>Recommended Work:</b>	X	Rehab		Replace	<b>Maintenance Needs:</b>	
	X	1-5 years		6-10 years	Urgent	1 year 2 years

<b>Element Group:</b>	Foundations		<b>Length:</b>	N/A		
<b>Element Name:</b>	Foundations (below ground level)		<b>Width:</b>	N/A		
<b>Location:</b>	North and South		<b>Height:</b>	N/A		
<b>Material:</b>	Cast-In-Place Concrete		<b>Count (items):</b>	2		
<b>Element Type:</b>			<b>Total Quantity:</b>			
<b>Environment:</b>	Benign	Limited Inspection		X		
<b>Protection System:</b>	None					Perform. Deficiencies
<b>Condition Data:</b>	Units	Exc.	Good	Fair	Poor*	
<b>Comments:</b>	Limited inspection. No evidence of instability or settlement at the time of inspection.					
<b>Recommended Work:</b>		Rehab		Replace	<b>Maintenance Needs:</b>	
		1-5 years		6-10 years	Urgent	1 year 2 years

<b>Element Group:</b>	Embankments & Streams		<b>Length:</b>	N/A		
<b>Element Name:</b>	Embankments		<b>Width:</b>	N/A		
<b>Location:</b>	NE, NW, SE and SW of Structure		<b>Height:</b>	N/A		
<b>Material:</b>	Stone and Vegetation		<b>Count (items):</b>	4		
<b>Element Type:</b>			<b>Total Quantity:</b>	6		each
<b>Environment:</b>	Benign	Limited Inspection				
<b>Protection System:</b>	Vegetation, Stone and Asphalt					Perform. Deficiencies
<b>Condition Data:</b>	Units each	Exc.	Good	Fair 4	Poor*	
<b>Comments:</b>	The embankments were steep and sparsely vegetated. Severe erosion was observed on the northeast embankment and in front of the north abutment.					
<b>Recommended Work:</b>	X	Rehab		Replace	<b>Maintenance Needs:</b>	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
- Repair						

<b>Element Group:</b>	Embankments & Streams			<b>Length:</b>	N/A		
<b>Element Name:</b>	Slope Protection			<b>Width:</b>	N/A		
<b>Location:</b>	NE, NW, SE and SW of Structure			<b>Height:</b>	N/A		
<b>Material:</b>	Vegetation, Stone and Asphalt			<b>Count (items):</b>	6		
<b>Element Type:</b>				<b>Total Quantity:</b>	6 each		
<b>Environment:</b>	Benign			Limited Inspection			
<b>Protection System:</b>	None						Perform. Deficiencies
<b>Condition Data:</b>	Units each	Exc.	Good	Fair	Poor*		
			1	4	2		
<b>Comments:</b>	The slope protection is not currently performing well. Asphalt was noted on the northeast embankment.						
<b>Recommended Work:</b>		Rehab	X	Replace	<b>Maintenance Needs:</b>		
	X	1-5 years		6-10 years	Urgent	1 year	2 years
- Replace							

<b>Element Group:</b>	Embankments & Streams			<b>Length:</b>	N/A		
<b>Element Name:</b>	Streams and Waterways			<b>Width:</b>	N/A		
<b>Location:</b>	West to East			<b>Height:</b>	N/A		
<b>Material:</b>				<b>Count (items):</b>	1		
<b>Element Type:</b>				<b>Total Quantity:</b>	1 each		
<b>Environment:</b>	Benign			Limited Inspection			
<b>Protection System:</b>							Perform. Deficiencies
<b>Condition Data:</b>	Units each	Exc.	Good	Fair	Poor*		
			1	0	0		
<b>Comments:</b>	The stream flows from west to east. No obstructions to flow was observed at the time of inspection.						
<b>Recommended Work:</b>		Rehab		Replace	<b>Maintenance Needs:</b>		
		1-5 years		6-10 years	Urgent	1 year	2 years

<b>Element Group:</b>	Accessories			<b>Length:</b>	N/A		
<b>Element Name:</b>	Signs			<b>Width:</b>	N/A		
<b>Location:</b>	Deck and Approaches			<b>Height:</b>	N/A		
<b>Material:</b>	Steel			<b>Count (items):</b>	4		
<b>Element Type:</b>				<b>Total Quantity:</b>	8 each		
<b>Environment:</b>	Benign			Limited Inspection			
<b>Protection System:</b>							Perform. Deficiencies
<b>Condition Data:</b>	Units each	Exc.	Good	Fair	Poor*		
			7	1	0		
<b>Comments:</b>	The northeast hazard sign had significant collision damage. The signs consisted of 4 hazard signs, 2 load posting signs, 1 speed limit sign, narrow bridge sign and 2 Tay River signs.						
<b>Recommended Work:</b>		Rehab		Replace	<b>Maintenance Needs:</b>		
		1-5 years		6-10 years	Urgent	1 year	2 years

Repair/Rehabilitation Required				
Element Group	Element	Repair/Rehabilitation	Priority	Cost
Deck	Deck Top	Replace	1 - 5 years	\$225,000
Barriers	Railing System	Replace	6 - 10 years	\$70,000
Barriers	Parapet Walls	Replace	6 - 10 years	\$10,000
Deck	Soffit - Thin Slab (Interior and Exterior)	Repair	6 - 10 years	\$30,000
Beams/ML'E's	Girders	Replace	1 - 5 years	\$60,000
Pier	Shafts/Columns/Pile Bents	Repair	1 - 5 years	\$12,000
Coatings	Structural Steel	Repair	1 - 5 years	\$10,000
Abutments	Bearings	Replace	1 - 5 years	\$100,000
Abutments	Abutment Walls	Repair	1 - 5 years	19,000
Abutments	Wingwalls	Repair	1 - 5 years	\$12,000
<b>Total Repair/Rehabilitation Cost</b>				<b>\$548,000</b>

Associated Work				
	Comments			Estimated Cost
<b>Approaches</b>	<input type="text"/>			<input type="text"/>
<b>Detours</b>	<input type="text"/>			<input type="text"/>
<b>Traffic Control</b>	<input type="text"/>			\$70,000
<b>Utilities</b>	<input type="text"/>			<input type="text"/>
<b>Right-of-Way</b>	<input type="text"/>			<input type="text"/>
<b>Environmental Study</b>	Additional environmental protection			\$20,000
<b>Other</b>	Dewatering			\$50,000
<b>Contingencies</b>	<input type="text"/>	10%	**	\$69,000
<b>Engineering</b>	<input type="text"/>	20%	**	\$138,000
<b>Total Associated Work Cost</b>				<b>\$327,000</b>
<b>Total Repair/Rehabilitation Cost</b>				<b>\$548,000</b>
<b>Total Cost</b>				<b>\$875,000</b>
<b>Tay Valley Township Share @ 100%</b>				<b>\$875,000</b>

\*\* If based on a percentage calculated values rounded-up to the nearest thousand dollars.

**Justification**

The structure is generally in fair to poor condition. The deck top, girder ends, pier column connections, structural steel coating, abutment bearings, abutment walls and wingwalls all evidenced severe deterioration. Due to the amount of deterioration throughout the listed elements replacement of structure is recommended in 1 to 5 years. The full extent of the rehabilitation required to address some of the elements, in particular the deck, will likely be more costly than replacing the bridge in it's entirety. An enhanced OSIM should be carrier out in 2020 to determine the extent of deterioration of the girders, piers and soffit.

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 1: North Approach Looking at Structure



Photo 2: South Approach – Medium to Severe Cracking, Light to Medium Raveling and Asphalt Patch

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 3: West Railing System



Photo 4: East Railing System – Collision Damage



**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 5: Northwest Concrete End-Post – Medium Scaling, Light Spalling and Light Abrasions



Photo 6: Southeast Hazard Sign

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 7: Exposed Concrete Wearing Surface



Photo 8: North End of Deck – Severe Delaminations, Light Spalling and Medium to Wide Cracking

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 9: East Exterior Girder – Light to Medium Corrosion



Photo 10: Northwest Girder End and Steel Bearing – Light to Medium Corrosion

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 11: Southeast Girder End – Light Corrosion and Excessive Debris on Bearing Seat



Photo 12: Northwest Bearings – Medium Corrosion and Deformations

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 13: Interior Soffit, Stringers and Floor Beams



Photo 14: East Exterior Soffit – Light Delaminations and Hairline to Narrow Cracking

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 15: North Beam Ends, Ballast Wall and Stringers



Photo 16: South Pier System – Light to Medium Corrosion

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 17: Northwest Pile Bent Connection – Severe Corrosion with Section Loss



Photo 18: Northeast Pier Footing and Pedestal – Light to Medium Scaling and Medium to Wide Cracking

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 19: Northeast Pier Pedestal and Bent Connection – Wide Crack and Medium to Severe Corrosion



Photo 20: North Abutment Wall – Severe Delaminations, Wide Cracking, Severe Scaling and Disintegration



**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 21: North Abutment on the East End – Severe Delaminations and Severe Erosion and Disintegration



Photo 22: Southwest Wingwall – Light to Medium Scaling

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road



Photo 23: Northeast Wingwall – Severe Erosion, Scaling and Disintegration




Photo 24: Stream Looking East - Outlet

**REPRESENTATIVE PHOTOGRAPHS**

Owner: Tay Valley Township  
Hwy/Road Name: Crow Lake Road

Structure Name: Bolingbroke Bridge  
Location: 0.1 km West of Bolingbrook Road




Photo 25: Stream Looking West - Inlet